Changes for Release 2.1.0.2 (19 March, 2009)

Resolved issues for Waterways Manager:

- [BUG:44424] User preferences not always being honored
- [BUG:50894] Windows Preferences for WDT Soils and Vegetal not working
- [BUG:56494] Simple Alignment - Error occurs if angle is blank
- [BUG:57059] Surface messaging - no reason provided when selected file doesn't contain a surface (different from Alignments)
- [BUG:57070] Preferences - Waterway Design parameters for Seeding width, Profile, and Cross-Section not saved
- [BUG:57110] New Surface - User is able to add a new surface with a blank name
- [BUG:57145] Save Waterway from the File menu not saving waterway
- [BUG:60216] Preferences - Default Channel Types not saved for waterway reaches
- [BUG:62272] WDT new Station Offset survey does not create an alignment
- [BUG:78025] Graphic Error - Reach Simulation Report

Changes for Release 2.1.0.1 (17 February, 2009)

- [BUG:60110] contouring timeout changed to 30 seconds
- [BUG:60110] contouring timeout message changed for better clarity
- [BUG:60335] fixed I/O exception when "calculate" button pressed in Cut/Fill

Changes for Release 2.1.0.0 (17 February, 2009)

- [BUG:51482] Tool-level checkboxes and report failures
- [BUG:53049] File, Save giving error message on first save
- [BUG:56639] LL Structure not updating on Legend or Map
- [BUG:57248] Text drawings lose font properties after move
- [BUG:58126] Survey Structures - user is able to create and save bad data causing an error when re-opened
- [BUG:58197] Some pop-up windows aren't persistent
- [BUG:58627] Simple Alignment - Error occurs if angle is blank
- [BUG:59606] Default file name when no ground surface is selected is _dummy_.txt
- [BUG:59834] Error creating Land-Leveling Structure without Ground Surface
- [BUG:59836] Error adding a second Station/Offset survey
- [BUG:60110] Adding breaklines hangs up EFT
- [BUG:60153] Application hangs on save
- [BUG:60335] Cut/Fill - wrong base surface file causes exception
- [BUG:60358] TIN holes in extreme surveys

Changes for Release 2.0.2.9a (22 January, 2009)

- updated EFT Framework help system content
- updated SET help system content
- [BUG:50902] Land-Leveling: survey import issue
- [BUG:53049] File, Save giving error message on first save
- [BUG:55190] Land Leveling Grid Report truncated large part of table
- [BUG:55278] WDT Reports do not work for SET Beta 2.0.2.9
- [BUG:55280] SET Beta causes many WDT printing errors
- [BUG:55281] Can't Print at all
- [BUG:55664] Incorrect volumes for structures
- [BUG:55666] Remove the Save buttons from the Cut/Fill Tab
- [BUG:55669] Wrong dialog window for Survey Data Reports

Changes for Release 2.0.2.9 (07 January, 2009)

- updated SET help system content

Changes for Release 2.0.2.8 (06 January, 2009)

- [BUG:53851] Remove data settings option for Alignment Stations and Alignment Offset Stations
- [BUG:54022] Deletion of target point from the survey causes problems
- [BUG:54840] Map Sheets can't handle apostrophe in sheet name/title
- [BUG:54899] Reports won't run alone
- [BUG:54904] Incorrect PC, PT in stakeout for decreasing alignment

Changes for Release 2.0.2.7 (11 December, 2008)

Resolved issues for Survey Manager:

- [BUG:26941] Point Translation doesn't work
- [BUG:44989] Add unit conversion option for importing of point files (meters to feet)
- [BUG:50057] Stationing convention incorrect
- [BUG:52307] Land-Leveling stakeout report omits border points
- [BUG:52996] Point Translation for XYZ surveys
- [BUG:53018] Drawing Legend Item - Right click options not working
- [BUG:53019] Project Points report fails
- [BUG:53020] Project Points report has extraneous sources of points
- [BUG:53030] Can't modify an alignment
- [BUG:53032] Map Sheet Preview not working on new survey
- [BUG:53046] Fatal error when opening a newly created S/O survey

Resolved issues for Waterways Manager:

- [BUG:39055] Alignment Report

Changes for Release 2.0.2.6 (14 November, 2008)

Resolved issues for Survey Manager:

- [BUG:28959] Zero point in S/O causes duplicate pt errors
- [BUG:48658] S/O entry goes fubar after crossing zero distance point
- [BUG:49200] Add pop-up tool to the Angle column in alignment table
- [BUG:49593] Need OK button on Legend Data Settings dialogs
- [BUG:49626] Text and Point drawings move on zoom
- [BUG:49631] Mouse wheel zooming needs adjustment
- [BUG:49959] Same alignment name is allowed within a manager
- [BUG:49966] Closing of survey manager with S/O did not close all the alignments in the legend
- [BUG:49988] Reduced S/O Survey Data Report not in survey order
- [BUG:50020] Insertion of alignment stations not working correctly
- [BUG:50057] Stationing convention incorrect
- [BUG:50063] Can't access right-click Map Sheet options on new manager
- [BUG:50065] Grid not printed in reports
- [BUG:50522] Tin sliver error interference with structure design

- [BUG:50548] Report dialog enables inapplicable reports
- [BUG:50874] Add alignment sketch capability
- [BUG:50885] Isopach map doesn't generate; locks up the program
- [BUG:50901] Land-Leveling: Waste/borrow tools not working
- [BUG:51027] Size of title block text and optional symbols too small on D-size output sheet
- [BUG:51028] Restrict the entry length of the Project Information to 40 characters; similar for designed by block
- [BUG:51029] Scale bar should be labeled
- [BUG:51041] Map sheets do not follow CAD standards policy
- [BUG:51049] Add User preferences for contours
- [BUG:51096] Report resultant slope
- [BUG:51098] Add Design Button to LL UI
- [BUG:51859] Structure UIs should indicate obsolete results in gray

---

Changes for Release 2.0.2.4 (26 September, 2008)

Enhancements to the EFT Framework:

- Temporarily removed the cleanup functionality, due to it causing InstallShield problems
- [BUG:30577] Need separate contour labels for major and minor contours
- [BUG:49633] Trouble with D size sheets
- [BUG:49638] Resizing map window not working correctly
- [BUG:49983] S2P blue dot doesn't appear before closing & reopening manager

---

Changes for Release 2.0.2.3 (22 September, 2008)

Resolved issues for Survey Manager:

- [BUG:49748] No saving of manager

Changes for Release 2.0.2.2 (19 September, 2008)

Enhancements to the EFT Framework:

- removes old-format examples directory if detected on startup. Use Help/Install Examples to refresh.
- [BUG:49546] SET locks up when trying to parse/display old-format example data

Resolved issues for Survey Manager:

- Fixed annoying double prompt after first save in newly created project
- [BUG:44457] Title block "designed by", "checked by", "Date", etc need changes
- [BUG:45973] Land Leveling Cut Fill Contours on Isopach Map
- [BUG:45975] Land Leveling Isopach Map Legend
- [BUG:48519] Unable to add border points
- [BUG:49071] New SurveyManager/import/save does not undirty the editor
- [BUG:49137] S/O Entry - order of points in project points table and PP report
- [BUG:49140] Radial - order of points in project points table and PP report
- [BUG:49219] Entering alignment curve data using coordinate method not working correctly
- [BUG:49375] Warning message on truncated structures inconsistent
- [BUG:49380] Breakline segment doesn't go with the snapped point
- [BUG:49482] S/O Alignment Curve & Stakeout report - Curve Data table - PC & PT stations to be in station format
- [BUG:49586] Add Structure without TIN error
- [BUG:49610] Failure of LL report when requested with other structures
- [BUG:49611] Failure of structure stakeout reports with survey of minimal points

- [BUG:49613] Round pit structure needs larger entry fields
- [BUG:49615] Map sheet legend item inactive after new survey manager created
- [BUG:49617] Contour labels not reliable

Changes for Release 2.0.2.1 (15 September, 2008)

Resolved issues for Survey Manager:

- [BUG:48519] Unable to add border points
- [BUG:49198] S/O Alignment Report - wrong angle convention in report
- [BUG:49345] Change to last column of Coord method of alignment table

---

Changes for Release 2.0.2.0 (12 September, 2008)

Enhancements to the EFT Framework:

- A pointer to the EFT web site has been added to the Help/About dialog
- [BUG:48965] Mapping view locks up
- [BUG:49291] Mapsheet can be defined when there is no map to associate it with

Resolved issues for Survey Manager:

- Some editors were wiping out the toolpath display and not restoring it
- [BUG:35540] Truncated Structure border not correct.
- [BUG:48519] Unable to add border points
- [BUG:48992] Can't access or save structures after encountering error message
- [BUG:48993] Encountering invalid TIN sliver messages and failed designs
- [BUG:49011] Error messages from previous structure design attempt persistent
- [BUG:49071] New SurveyManager/import/save does not undirty the editor
- [BUG:49120] Inputted structure sizes and slopes change back to default if Equal Side Slopes checkbox is unchecked
- [BUG:49174] Borders should not contain un-TINned area
- [BUG:49199] S/O Alignment Curve & Stakeout Report - several errors noted
- [BUG:49234] Error in printing the reduced s/o survey data report with other reports